

American Legion Post



American Legion Building, Centre Hall, PA

Hard Water Problems

Located in an area of notoriously hard water, this American Legion Post 779, in Centre Hall, PA, had its share of hard water problems. Outside of using a lot of chemicals, cleaners and costly labor, the Board of Directors knew of no other alternatives. They figured "water was water" and nothing could be done about it.



Heat Exchanger for the American Legion building

Some of their problems included this heat exchanger, where lime and calcium deposits made it a constant nightmare for the maintenance crew. The cost of cleaning the exchangers was a "fixed expense" for the accounting department!

How Ugly!

Another problem associated with hard water involved the bathrooms, where scale was a serious problem. Pictured here is one of their toilets. Dangerous acid and a chisel were actually required to clean the toilets.



American Legion Toilet 5/17/97

The Solution



ScaleBlaster™ installed Spring, 1997

A ClearWater dealer stopped in and told them about the ScaleBlaster™, an electric descaler that would solve all their problems without using chemicals and chisels! The ScaleBlaster™ was installed in the Spring of 1997.

The Final Results... Beautiful!

Nobody said toilet bowls are a pretty sight, but compared to the way this American Legion's toilet bowls looked before the ScaleBlaster™ was installed, they sure are now! Instead of using acid and chisel to clean the toilets, only a brush is required! The heat exchangers also cleaned up dramatically, too.



American Legion toilet 6/15/97--Cleaned with brush only!

American Legion, Club 779
Old Fort Intersection
Centre Hall, PA 16828
814-364-9416

December 2, 1997

ClearWater Enviro Technologies
1054 Kapp Dr.
Clearwater, FL 34625

Dear Sir,

We wanted to let you know how extremely pleased we are with the installation of your Scale Blaster Unit.

We initially had it installed in May of 1997 after years of having extreme difficulties with our heat exchangers building up with lime and calcium deposits and having expensive bills to have the exchangers cleaned. We hoped that the Scale Blaster unit would solve the problem. In addition, the build-up in the toilets in the bathrooms was so bad that they couldn't be cleaned without dangerous acid or chipping it away with a small chisel like your representative did to determine how thick the build-up was. After about one and a half months, the build-up in the toilets had turned to mush and with a simple toilet brush, we simply brushed the build-up away and the toilets looked as if they were brand new. Since then, there has been no additional build-up and cleaning is a very easy and simple operation with no chemicals needed. It's been great! In addition, we have not had any problems with our heat exchangers since the installation of your Scale Blaster unit.

I had to enclose some "before" and "after" pictures of our toilets because we are so amazed that this unit works so well with absolutely no chemicals or maintenance or cost.

Sincerely,

Debbie Auman Club Steward
Debbie and the Board of Directors, American Legion Club 779

Letter written by
Debbie Auman and
the Board of
Directors for the
American Legion
Post 779.



A Revolution in Water Purification
Clearwater, Florida



World-Wide Distribution
in over 75 countries

Corporate Office

1166 Kapp Drive
Clearwater, FL 33765

Toll Free 1.800.756.7946
Phone 727.562.5186
Fax 727.562.5187